

# Course 445

## Inspection of Particle Control Devices

August 31-September 2, 2010

### AGENDA

**LOCATION**  
Nashville, Tennessee

**MODERATOR**  
J.W. Crowder

DAY & TIME	SUBJECT	SPEAKER
<b><i>Tuesday, August 31</i></b>		
9:00	Introduction	J. Crowder
9:15	Pre-Test	
9:45	BREAK	
10:00	Baseline Inspection Technique	J. Crowder
10:45	Inspection of Cyclones	J. Crowder
12:00	LUNCH	
1:00	Inspection of Cyclones (cont'd)	J. Crowder
1:45	Inspection of Fabric Filters	J. Crowder
2:30	BREAK	
2:45	Inspection of Fabric Filters (cont'd)	J. Crowder
4:30	ADJOURN	
<b><i>Wednesday, September 1</i></b>		
9:00	Inspection of Fabric Filters (cont'd)	J. Crowder
10:15	BREAK	
10:30	Inspection of Wet Scrubbers	J. Crowder
12:00	LUNCH	
1:00	Inspection of Wet Scrubbers (cont'd)	J. Crowder
2:30	BREAK	
2:45	Inspection of Electrostatic Precipitators	J. Crowder
4:00	Review of Pre-Test	J. Crowder
4:30	ADJOURN	
<b><i>Thursday, September 2</i></b>		
9:00	Inspection of Electrostatic Precipitators (cont'd)	J. Crowder
10:30	BREAK	
10:45	Measurement of Inspection Parameters	J. Crowder
12:00	LUNCH	
1:00	Preparation of Flow Charts	J. Crowder
2:15	BREAK	
2:30	Post-Test	
3:30	Course Critique	
4:00	ADJOURN	

---

Jerry W. Crowder, Ph.D., P.E.  
Crowder Environmental Associates, Inc.  
6946 Dove Creek  
Wylie, Texas 75098-7750  
Tel: 972-442-7702  
Fax: 972-442-0707  
Cell: 972-839-5954  
E-mail: jwcrowder@verizon.net